

$S_p = 2,5 \text{ mA/V}$
 $R_i = 80 \text{ k}$
 $P_a = \text{max. } 8,5 \text{ W}$

$S_T = 0,3 \text{ mA/V}$
 $R_i = 19 \text{ k}$
 $\mu = 6$
 $P_a = \text{max. } 1 \text{ W}$

